		SE	ECTION	V - HEA	LTH HAZARD DATA	
THRESHOLD LI Rat Oral	LD50 > 2	.0 gm/kg	(estin	nated).		
EFFECTS OF OV	VEREXPOSU		NING!	May caus	e eye irritation, skin sensitization, or	
other all						
EMERGENCY A	ND FIRST A	ID PROCEDU	RES	contact	occurs, wash skin immediately with soap	
and water	. Flush	eyes im	mediate	ly with	plenty of water.	
			·			
	· · · · · · · · · · · · · · · · · · ·		SECTIO	NVI - R	EACTIVITY DATA	
STABILITY	UNSTA	UNSTABLE		conditions to Avoid Follow recommended storage conditions.		
	STABL	STABLE				
INCOMPATABIL	ITY (Materia	ls to avoid)				
HAZARDOUS DE	ECOMPOSITI	ON PRODUC	TS			
HAZARDOUS		MAY OCCUR		Х	Exothermic - avoid heating too high and	
POLYMERIZATI		WILL NOT OCCUR			large masses particularly when curing	
agents are	e added.					

SECTION VII - SPILL OR LEAK PROCEDURES						
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED	Soak up or scrape excess material.					
Clean residue with solvents.						
·	4					
WASTE DISPOSAL METHOD  Landfill or controlled bur	ning as regulated by all					
governmental agencies.						

	SECTION VIII - SPECIA	L PROTECTION	NINFORMATION
RESPIRATORY PE	ROTECTION (Specify type)		
VENTILATION	LOCAL EXHAUST Highly rec	commended	SPECIAL
	MECHANICAL (General)		OTHER
PROTECTIVE GLOVES Rubber		EYE PROTECTION Safety glasses or goggles	
OTHER PROTECT	IVE EQUIPMENT		

SECTION IX - SPECIAL PRECAUTIONS							
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING		Follow recommended storage conditions.	ons.				
OTHER PRECAUTIONS	Read container labels						
		ANSI Classification 4					

PAGE (2)